

Apr 13th - Apr 17th

Past Proceedings: 4th International Conference on Case Histories in Geotechnical Engineering (1991)

Multiple Authors

Follow this and additional works at: <http://scholarsmine.mst.edu/icchge>



Part of the [Geotechnical Engineering Commons](#)

Recommended Citation

Authors, Multiple, "Past Proceedings: 4th International Conference on Case Histories in Geotechnical Engineering (1991)" (2004). *International Conference on Case Histories in Geotechnical Engineering*. 4. <http://scholarsmine.mst.edu/icchge/Sicchge/session13/4>

This Article - Conference proceedings is brought to you for free and open access by Scholars' Mine. It has been accepted for inclusion in International Conference on Case Histories in Geotechnical Engineering by an authorized administrator of Scholars' Mine. This work is protected by U. S. Copyright Law. Unauthorized use including reproduction for redistribution requires the permission of the copyright holder. For more information, please contact scholarsmine@mst.edu.



**FOURTH INTERNATIONAL CONFERENCE ON
CASE HISTORIES IN
GEOTECHNICAL ENGINEERING
March 8-12, 1998**

TABLE OF CONTENTS

Preface

Disclaimer

Steering Committee

Organizing Committee

Paper Review Committee

Conference Program

Guest Speakers

Meet Our Authors

First Case Histories Conference 1984

Second Case Histories Conference 1988

Third Case Histories Conference 1993

Keynote Lecture

**Ralph B. Peck
(USA)**

Creating Case Histories the Hard Way. KN00

State of The Art Lectures

**E. W. Brand
(China)**

**Forensic Engineering Applied to Slope Failure in
Hong Kong. SOA-1***

***Withdrawn**



- Jean-Lou Chameau**
(USA) **Measurement and Analysis of Civil Engineering Vibrations. SOA-2**
- W. D. Liam Finn**
(Canada) **Estimating Post-Liquefaction Displacements in Embankment Dams and Prioritizing Remediation Measures. SOA-3**
- Dr. Susumu Iai**
(Japan) **Rigid and Flexible Retaining Walls During Kobe Earthquake. SOA-4**
- Suzanne LaCasse**
F. Nadim
(Norway) **Risk and Reliability in Geotechnical Engineering. SOA-5**
- R. H. Ledbetter**
(USA) **Remediation of Major Earth Dams. SOA-6****
- Robert Mair**
(UK) **Recent Experiences of Tunnelling and Deep Excavations in London. SOA-7**
- Tamotsu Matsui**
(Japan) **Foundation Damage of Structures in Kobe Earthquake and Remediation. SOA-8**
- R. Kerry Rowe**
(Canada) **Past and Future of Landfill Engineering Through Case Studies. SOA-9**
- Joseph P. Welsh**
(USA) **State of the Art of Soil Improvement with Case Histories. SOA-10**
- John H. Schmertmann**
John A. Hayes
Thomas Molnit
Jorg Osterberg
(USA) **O-Cell Testing Case Histories Demonstrate the Importance of Bored Pile (Drilled Shaft) Construction Technique. SOA-11**
- Special Lectures**
Clyde N. Baker
(USA) **Foundation Design and Performance of the World's Tallest Building, Petronas Towers. SPL-1**
- K. Rainer Massarch**
(Sweden) **Soil Improvement Projects. SPL-2***
- Dr. Pedro Simao**
Seco e Pinto
(Portugal) **A Recent Difficult Foundation Problem: The Case of the New Teja Bridge. SPL-3**
- R. S. Steedman**
(UK) **Seismic Design of Cellular Cofferdams. SPL-5**

***Withdrawn**

**** Not received.**



Session I
"Case Histories of Foundations"

- | | |
|--|--|
| R. David Charles
(USA) | Case History of Two Buildings Experiencing Large Post Construction Settlements, Wilmington, Delaware. 1.01 |
| A. B. Fadeev
V.N. Paramonov
V.K. Inozemtcev
V.A. Lukin
E.M. Perley
(Russia) | Settlements of Neighboring Buildings During Piling Works. 1.04 |
| Amer A. Al-Rawas
M. Qamaruddin
(Sultanate of Oman) | A Case Study on Expansive Soils and Rocks of Al-Khod in Northern Oman. 1.05 |
| Braja M. Das
(USA)
Eun Chul Shin
(South Korea) | Cyclic Load-Induced Settlement of Foundations on Clay. 1.07 |
| John R. Davie
Kenneth R. Bell
M. B. Fitzsimmons
Daniel A. Haggerty
(USA) | Heavy Crane Foundations on Soft Clay. 1.09 |
| Md. Nurul Amin
Sabina Shahnaz
Sonia Shahnaj
(Bangladesh) | Performance of Bored Cast-In-Situ R.C.C. Piles in Bangladesh. 1.10 |
| Chu-Eu Ho
Ching-Heng Lim
(Singapore) | Barrettes Designed as Friction Foundations:
A Case History. 1.11 |
| Bouafia Ali
(Algeria) | Experimental Analysis of Large Lateral Displacements of Piles in Centrifuge. 1.12 |
| K. M. Murtagh
E. B. Kinner
R. E. Bertolino
C. Soydemir
(USA) | Expansion and Rehabilitation of The State Fish Pier in Gloucester, Massachusetts. 1.13 |
| D. S. Tolia
(India) | Validity of Peck, Hanson and Thornburn's SPT Correction Method and Soil Pressure Chart. 1.16 |
-



- Sven Hansbo
Leif Jendeby
(Sweden) A Follow-Up of Two Different Foundation Principles. 1.17
- J.L.M. Clemente
A. Desai
H. Senapathy
L.W. Young, Jr.
(USA) Foundation Performance of Large Diameter Tanks. 1.18
- F. Colleselli
G. Cortellazzo
(Italy) Behavior of the Underpinning of a Building in Venice. 1.19
- N. Thasnanipan
W. Teparaksa
A.W. Maung
Ganeshan Baskaran
(Thailand) Design, Construction and Behavior of Bored Cast In-Situ
Concrete Piles in Bangkok Sub Soil. 1.20
- Alan J. Lutenegger
Michael T. Adams
(USA) Bearing Capacity of Footings on Compacted Sand. 1.21
- Nasser Massoudi
(USA) Foundation Construction on Random Fill. 1.22
- Roy E. Olson
Magued G. Iskander
(USA) Axial Load Capacity of Piles in Sand. 1.23
- Gary Axelsson
(Sweden) Long-term Increase in Shaft Capacity of Driven Piles in Sand. 1.25
- Carole L.B. Mitchell
(USA) Design and Construction of The Seattle Symphony's Benaroya Hall
Above an Old Railroad Tunnel. 1.27
- G. Ramasamy
G. Kalaiselvan
(India) A Case Study on Settlement of Oil Storage Tank Foundations. 1.33
- Martin B. Hudson
(USA) Osterberg Load Cell Testing of a Deep Reinforced
Concrete Pile. 1.36
- Gerald P. Raymond
(Canada) Track and Support Rehabilitation 1975 on Black Mesa &
Lake Powell Railroad. 1.38
- P. C. Su
Y. C. Chen
J. Lin
C. F. Chen
(Taiwan) Soil Improvement for Storage Tank Foundations 1.40
-



- W. Akili
Robert M. Jackson
(Qatar) Shallow Foundations on a Diagenetic Limestone
Formation in Qatar. 1.41
- U. N. Sinha
(India) Failure of Buildings on Mound- A Case Study. 1.42
- Jie Han
(USA) Ground Modification by a Combination of Dynamic Compaction,
Consolidation, and Replacement. 1.44
- K. Zand Parsa
(Iran) Foundations Reinforcement of Old Ala Building. 1.47
- Sasha D. Milovic
Zuhtu S. Ozden
George S.W. Chow
(Canada) Calculated and Observed Settlements of Multistory Building
Founded on Loess. 1.48
- Elias Sotiropoulos
Elias Alkalais
(Greece) Foundation Problems of a Cable Stayed High Bridge
and Its Approaches. 1.49
- Takahide Horiuchi
Yukihiko Kani
(Japan) Deformation Modulus of Soil at the Tip of a Bored Pile. 1.50
- Raghu N. Dass
Vijay K. Puri
(Illinois) Load Tests on Drilled Shafts for Highway Bridges. 1.52L
- S. Sudarshan
C.S. Viswanatha
T. S. Nagaraj
(India) Restoration of Equalization and Aeration Tanks of Effluent Treatment
Plant at the Mysugar Factory, Mandya, Karnataka, India. 1.54N
- Shamsher Prakash
(USA)
M. H. Chen
(Taiwan) Non-Linear Lateral Pile Deflection Predictions in Clays. 1.55

Session II

“Case Histories of Slopes, Dams and Embankments”

- Buddhima Indraratna
I. W. Redana
(Australia) Effect of Smear Due to Vertical Drains on the Behavior of Two Embankments
Constructed on Soft Clay. 2.04
- David J. Kerkes
(USA) Lessons Learned from the Analysis of a Wet Core Dam. 2.05
-



- Masaki Kawasaki
Yoshikazu Yamaguchi
Hitoshi Yoshida
(Japan)
- Grouting in Consideration of Predominant Direction of Joints
in Rock Masses. 2.06
- Indra Prakash
A. B. Yyas
(India)
- Geotechnical Problems and Treatment of Weathered Rock Seams Occurring in the
Foundation of Karjan Dam, Western India. 2.07
- L. A. Bressani
A. V. D. Bica
W.Y.Y. Gehling
M. R. Bianchini
(Brazil)
- A Slope Instability Case History Involving Swelling Clay
in Southern Brazil. 2.10
- Y. Yamaguchi
Y. Imabayashi
Hitoshi Yoshida
T. Sakamoto
(Japan)
- Survey of Seepage Through Heightened Earthfill Dam with
High-Density Electrical Prospecting Method. 2.11
- Bujang B.K. Huat
(Malaysia)
- An Investigation of an Embankment Failure in Soft Clay. 2.14
- A. K. Gupta
D. S. Tolia
(India)
- Major Landslides in Sikkim-Analysis, Correction and
Protective Measures: A Case Study. 2.15
- Dipak Mukherjee
Satish Kumar
(India)
- Use of Geofabrics for Controlling Landslides-
Case Histories. 2.17
- Isao Nagayama
Michio Ota
Yosuke Niitaka
Masahiko Yamashita
(Japan)
- A Study on Prediction of Improvement of Watertightness
of Rock Mass by Grouting. 2.18
- Michael Long
John Godden
(Ireland)
- The Performance of Turlough Hill Upper Reservoir. 2.20
- A.N. Hussein
(Malaysia)
A. McGown
(UK)
- The Behavior of Two Trial Embankments at Perlis, Malaysia
with Different Rates of Construction. 2.22
-



- K. N. Gunalan
Thomas S. Lee
Si Sakhai
(USA)
Stage 1 Geotechnical Studies for Interstate 15 Reconstruction Project, Salt Lake County, Utah. 2.24
- Brent H. Carter
Richard A. Link
(USA)
Safety of Dams Modifications of Ochoco Dam Crooked River Project, Oregon. 2.25
- Mary P. Perlea
Kathleen E. Lust
Robert L. Pearce
Charles W. Detrick
(USA)
Repair of Scour Holes and Levees after the 1993 Flood. 2.26
- Richard L. Bateman
Francke C. Walberg
(USA)
Pile Design Procedure for Stabilizing Channel Slopes. 2.28
- W. H. Gu
R. F. Dawson
N. R. Morgenstern
P. K. Robertson
(Canada)
A Case History of Liquefaction Flow Failures in Mountainous Mine Waste Dumps. 2.29
- Dwikorita Karnawati
(Indonesia)
Natural Slope Failure on Weathered Andesitic Breccia in Samigaluh Area, Indonesia. 2.34
- Zbigniew Mlynarek
Wojciech Tschuschke
Jedrzej Wierzbicki
(Poland)
Procedure for In-Situ Evaluation of Geotechnical Parameters of High Dams. 2.37
- D. V. Singh
Jai Bhagwan
(India)
Case Study on Landslide Investigations in Himalayas. 2.38
- Kishor Kumar
R. K. Panigrahi
(India)
Instrumentation, Monitoring and Analysis of A Landslide- A Case Study. 2.40
- Russell L. Owens
(USA)
Seismic Evaluation, Soil-Cement Mix Wall and Outlet Pipe Installation, Ivins Bench Dam, Utah. 2.43
- E. Sotiropoulos
P. Papanikolaou
(Greece)
B. Dendrou
(USA)
Groundwater Conditions and Drainage of a Large Slide. 2.44
-



- Anton Chirica
Rolland Mlenajek
Andrei Olteanu
Cristian Banciu
(Romania) Study of Ground Movement in a Mining Area. 2.50L
- Shri Pal
(India) Arresting the Moving Slopes of Andamans-A Case Study. 2.51L
- W. Ken Beck
(USA) The Tale of Two Slides. 2.52L
- Kenneth M. Berry
Thomas L. Cooling
(USA) Landslides on Shale in Southern Illinois. 2.53
- Khalidoun Fahoum
Philip A. Jozwiak
(USA) Remediation of River Des Peres Slope Failure-A Case History. 2.56
- Sanjeev Kumar
(USA) Stabilization of an Existing Slope Supporting Underground Storage Tanks at the Top. 2.58

Session III

“Case Histories of Geotechnical Earthquake Engineering”

- Vassilios K. Magginas
(USA) Case History on the Foundation and Site Liquefaction Potential Evaluation for the Renovation of a One-Hundred Year Old Building. 3.01
- Gerald Kasman
Marshall Lew
Paul Elliott
(USA) Investigation of Ground Cracking at the Van Gogh Street School, Granada Hills, California. 3.05
- Carlos M. Sevilla
Joseph M. Gilroy
John Jenkins
(USA) Results of Dynamic Testing on Friction H-Piles. 3.06
- Tomoya Iwashita
Akira Nakamura
Shinji Yokoyama
Norihisa Matsumoto
Hitoshi Yoshida
(Japan) Factor Analysis of Damage to Small Earth Dams Due to the 1995 Hyogoken-Nambu Earthquake. 3.07
-



- Shyamal Mukerjee
Bhagwat Lavania
(India) Soil Liquefaction in Nepal-Bihar Earthquake of August 21, 1988. 3.08
- Katsumi Ozeki
Ikuo Katayama
(Japan) On the Behavior of Longitudinal Strain of a Buried Pipe Subjected
to Ground Spread Caused by Liquefaction Observed in Centrifuge
Model Tests. 3.11
- Jagadish R. Joshi
Richard C. Lee
(USA) Ground Motion Measurements from the Demolition of
Steel Towers. 3.15
- Narendra Kumar
V.K. Talwar
R. K. Pal
(India) Sinkholes in Earth Dam Kota Barrage (India). 3.16
- Masayuki Sato
Hiroyuki Watanabe
Satoshi Katayama
(Japan) Study on Mechanism of Caisson Type Sea Wall Movement
During Earthquake. 3.18
- Takahiro Sakata
Kenji Matsui
Yoshito Maeda
Hidetoshi Ochiai
(Japan) Lateral Loading Tests in the Pit for A Large-Diameter
Deep Pile. 3.19
- Ray Knox
David Stewart
(USA) Morphoseismic Features in the New Madrid Seismic Zone (Central USA) and their
Implications for Geotechnical Engineering. 3.22
- A. Elgamal
R. Dobry
Z. Yang
(USA)
E. Parra
(Venezuela) Soil Dilatation and Shear Deformations During Liquefaction. 3.24
-



Session IV
“Case Histories of Engineering Vibrations”

- Shamsher Prakash
Y. Tseng
(USA) Predictions of Vertically Vibrating Foundation Response with Modified Radiation Damping. 4.02
- Herke G. Stuit
(The Netherlands) Test Track Low Frequency Vibrations Reducing Measure Near Oosthuizen. 4.03
- William J. Prosser
George Manyando
Thomas J. Mottin
Gary M. Andruska
(USA) Vibration Mitigation for Brewery Stockhouse Demolition. 4.04
- Hideo Tsuboi
Tamotsu Matsui
(Japan) Case Histories and Vibratory Characteristics of Vibro-Driven Piles. 4.05
- Yang Xianjian
Jiang Bei
(China) Radiation Damping of Soil -Foundations Systems. 4.06
- Kiyoshi Hayakawa
Yukihiko Kani
Noriyuki Matsubara
Tamotsu Matsui
(Japan)
Richard Woods
(USA) Ground Vibrations Isolation by PC Wall-Piles. 4.07
- Shamsher Prakash
D.Nampoothiri
(USA) On Prediction of Dynamic Response of Horizontal Vibrations. 4.09

Session V
“Case Histories of Retaining Structures and Deep Excavations”

- M. S. Wang
(China)
X. Wu
M. C. Wang
(USA) Failure of Excavation Bracing System for New World Plaza at Changchun in China. 5.01
- Linbang Wang
(USA) An Anchored Band Bracing System for Deep Excavations in Clay. 5.02
-



- | | |
|---|---|
| Wanchai Teparaksa
Narong Thasnanipan
Aung Win Maung
Wei Shixin
(Thailand) | Prediction and Performance of Short Embedded Cast In-Situ Diaphragm Wall for Deep Excavation in Bangkok Subsoil. 5.04 |
| Young-Nam Lee
Seung-Won Lee
(Korea) | Excavation Behaviour of Soft Marine Clay Deposit in South Korea. 5.06 |
| Carole L.B. Mitchell
Monique A. Nykamp
(USA) | Shoring Analysis, Design and Construction at the Seattle Symphony's Benaroya Hall. 5.08 |
| Cai Yuanqiang
Wu Shiming
Chen Yunmin
Xu Changjie
(China) | Behavior of Double-Row Pile Retaining Structure for Deep Excavation in Soft Clay. 5.09 |
| Kevin W. McLain
(USA) | Soil Nailing: The MoDot Experience. 5.10 |
| Xu Changjie
Cai Yuanqiang
Wu Shiming
(China) | Behavior of Braced Deep Excavation in Soft Soils. 5.11 |
| Jean-Claude Blivet
Jean-Pierre Gourc
(France) | Large Retaining Structure Reinforced by Geosynthetics French Case Histories. 5.12 |
| Thomas S. Lee
Steven H. Brandon
(USA) | Geotechnical and Geologic Features of U.S. 189 in Provo Canyon, Utah. 5.13 |
| Theodore A.
Thomson, Jr.
Alan J. Lutenegeger
(USA) | Passive Earth Pressure Tests on an Integral Bridge Abutment. 5.15 |
| Minh Phong Luong
(France) | Abnormal Wall Movements of a Steel Silo Caused by Paddy Rice Storage. 5.17 |
| Wolfgang H. Roth
Alexander Delnik
(USA) | Numerical Modeling of a Crib-Wall Failure. 5.18 |
| J. K. Jain
A. K. Saxena
Sanjay Kumar
Shrivastava
(India) | Pier Failure of Bridge and Geotechnical Investigation - A Case Study. 5.19L |
-



Session VI
“Case Histories of Geological, Rock and Mining Engineering including Underground Structures and Excavations”

- | | |
|---|--|
| Nina N. Fotieva
Nikolay Bulychev
(Russia) | Case Histories of Designing Tunnel Linings in Seismic Regions. 6.01 |
| B. Huang
L. Mohammad
(USA)
Jianming Zhu
Xiaoping Zhu
(China) | Design, Construction and Monitoring for the Excavation of Shanghai World Plaza. 6.04 |
| David L. Mathews
Vlad G. Perlea
Francke Walberg
Douglas R. Anderson
(USA) | Erosion and Repair of Unlined Spillway Chute Excavated in Rock. 6.05 |
| Massoud Palassi
John A. Franklin
(Canada) | Tunnex: An Expert System for Tunneling Through Rock. 6.06 |
| R. K. Goel
J. L. Jethwa
A. K. Dube
(India) | Experiences of the Support Designs in the Two Large Underground Openings in India. 6.07 |
| J. C. Chern
C. W. Yu
H. C. Kao
(Taiwan) | Tunneling in Squeezing Ground. 6.08 |
| Siamac Vaghar
Dan J. Bobrow
(USA) | Comparison of Two Excavation Support Systems in Clay; Central Artery/Tunnel, Boston, Massachusetts, USA. 6.09 |
| Edmund Medley
Christopher Delp
(USA) | Of Sewers, Sinkholes, and Safes: The Investigation of the Sea Cliff Incident, December 11, 1995, San Francisco, California. 6.10 |
| Michael Kavvadas
(Greece) | Analysis and Performance of the Natm Excavation of an Underground Station for the Athens Metro. 6.11 |
| Borut Petkovsek
Lojze Bevc
(Slovenia) | Remedial Works in the Ljubelj Tunnel. 6.12 |
| Paul M. Santi
(USA) | Stability and Permeability of Fluid Retention Berms Constructed from Highly Weathered Bedrock. 6.16N |
-



S. Kwon
J. W. Wilson
(USA) Investigation of the Influence of the Clay Seams Around an Underground Excavation
in Rock Salt. 6.17

Hong Li
Gang Li
(China) A Computer Aided Rock Mass Classification for Rock Slopes. 6.18N

Session VII

“Case Histories of Soil Improvement, Grouting, Geosynthetics, Dynamic Compaction, Vibroflotation, Blasting and other Methods including Geo Economics”

I. I. Broid
G. V. Melnik
(Russia) Use of Jet Grouting Method for Elimination of Suffusional Destructions
of Sand Backfilling of Sheet Pile Wharf. 7.01

Suji Somasundaram
Gamini Weeratunga
Kris Khilnani
(USA) Ground Improvement at the Queensway Bay Downtown Harbor,
Long Beach, California. 7.03

G. Varosio
(Italy) A Non Destructive Testing Program for a Group of Jet
Grouting Columns. 7.04

Joy J. Lee
John M. Tehaney
(USA) Selection and Design of Foundations for the I-15/US 95 Interchange,
Stage II Improvements - A Case Study. 7.05

Kaushik Mukherjee
(India) Performance Prediction and Uses of PV Band Drains under the
Embankments on Soft Marine Clays of Bangkok. 7.06

A. Benslimane
I. Juran
S. Hanna
S. Drabkin
(USA)
S. Perlo
R. Frank
(France) Seismic Retrofitting Using Micropile Systems Centrifugal Model
Studies. 7.07

A. K. Gupta
Satish Kumar
D. S. Tolia
(India) Lime Slurry Injection, Lime Piles and Stone Columns for
Improvement of Soft Soils- Field Trials. 7.10

John Conway
(Puerto Rico)
Tom Novak
(USA) Grouting Evaluation Program of the Best Methods for Use of Microfine
and Portland Cements During Treatment of the Rock Foundation
at the Portugues Dam. 7.11



- Kejing Chen
Robert Lo
(Australia)
Huishan Liu
(China)
- Treatment of Soft Soils by Dynamic Compaction. 7.12
- Xiaohong Bai
Jungang Jia
Qiuxue Yang
(China)
- A Case History of Ground Treatment for a Power Station in China. 7.13
- Steven J. Winter
Victor Omelchenko
(USA)
- Red Onion Mountain Maximum Security Prison- A Case Study in Ground Improvement. 7.14
- Eun C. Shin
Bang-Woong Shin
(Korea)
- Construction of Incheon International Airport. 7.17
- Roberto A. Lopez
Mathew J. Francis
Kyle M. Rollins
Scott W. Davis
Zoran Batchko
(USA)
- Composite Ground Modification System: Vibroreplacement and Dynamic Compaction, Salt Lake County Detention Center, Utah. 7.18
- Alan J. Lutenege
Gerald A. Miller
(USA)
- Tension Tests On Drilled Micropiles In A Stiff Clay. 7.20
- A. K. Gupta
Jai Bhagwan
B. C. Joshi
(India)
- Observations on Landslide Incidences in Himalayas in Kashmir Area. 7.21
- A.K. Gupta
O.P. Yadav
Jai Bhagwan
(India)
- Field Experiments on Jute Soil Stabilisers. 7.23
- Carlos S. Oteo
Jose M. Delgado
German Burbano
Luis M. Sopena
(Spain)
- Soil and Site Improvements of the Marsh Soils in Puerto De Santa Maria Highway (Cadiz, Spain). 7.24
- Kyle Rollins
Kenneth Murphy
Shaun Dustin
Jerry Bishop
(USA)
- Soil-Nailed and Tie-Back Wall Construction Using Hollow Nails. 7.25
-



- Cameran Mirza
(Canada)
Robert K. Barrett
(USA)
- Shri Pal
(India)
- Ion Stanculescu
Florian Braniste
Ion Borsaru
(Romania)
- Mike Alizadeh
Sanjeev Kumar
(USA)
- Guidelines for Sealing Geotechnical Exploratory Holes. 7.27
- Protection of Kamorta Island From Coastal Erosion -
A Case Study. 7.34L
- Investigation of Landslides Affecting a Romanian Railway. 7.35N
- Soil Improvement in Flood Plain of the Mississippi River Using Pre-Load Fill. 7.37

Session VIII

“Case Histories of Forensic Engineering “Where Things Went Wrong”

- V. S. Hope
C.R. I. Clayton
M. C. Matthews
(UK)
- J. Richard Cheeks
(USA)
- Walter W. Hays
(USA)
- Matthew A. Dettman
(USA)
- Wayne A. Ericson
Ted J. Smith
(USA)
- An Investigation into the Causes of Building Cracks on the
Rear Scarp of a Major Landslip. 8.01
- It's Not What You Pay; It's What It Costs You
A Geotechnical Engineering Case Study. 8.02
- Case Histories of Damaging Earthquakes. 8.04
- Sinkhole Dropouts Due to Underground Utility Installation
on Construction Sites. 8.06
- Is It A Sinkhole? 8.08

Session IX

“Case Histories of New Solutions to Traditional Geotechnical Problems”

- Takaharu Shogaki
Hayato Moro
Minoru Matsuo
(Japan)
- Sudhir Mathur
Praveen Kumar
A.V.S. R. Murty
(India)
- Case Histories for Settlement Analysis in Ground Improved
by Vertical Drain. 9.01
- Steel Industry-Wastes as New Materials for Road
Construction. 9.03



- Ph Gotteland
G. Bossonney
D. Coulon
(France)
An Ecotechnical Alternative: An Embankment of Incinerated Municipal Solid Waste. 9.04
- Wei Xinjiang
Xia Tangdai
(China)
Research on Crack Depth Measurement in Concrete by Using Rayleigh Waves. 9.05
- Thomas Blackburn
Tom M. Farrell
(USA)
Shopping Center Saved by Short Aggregate Piers. 9.06
- John M. Benson
Donald R. Snethen
(USA)
Experimental Approach Embankments at Salt Fork River Bridges on US 177 and Their Initial Performance. 9.07
- Anthony L. DiPiero
Richard D. Lewis
Robert Ross
S. R. Honeycutt
(USA)
Identification of Potential Seepage Locations Along the Herbert Hoover Dike, Lake Okeechobee FL., by Electromagnetic Geophysical Method; Prediction and Confirmation. 9.08
- T. C. Kim
S. Q. Ahmad
T. J. Kazmierowski
(Canada)
A Case Study of the Application of Lightweight Fill for the Restoration of an Interchange Ramp. 9.10
- Carsten H. Floess
H. Moo-Young, Jr
Thomas F. Zimmie
Warren A. Harris, IV
(USA)
A Municipal Landfill Cover with a Paper Sludge Barrier Layer. 9.13
- Lenka S. Timiovska
(Macedonia)
Geotechnical Risk and Reliability from Theory to Practice. 9.15
- D. G. Anderson
C. C. Sundberg
R. J. Robertson
(USA)
Failure of a Pipeline in an 800-Year Old Debris Fill. 9.16L
- Anton Chirica
Mircea Galer
(Romania)
Stability Analysis Corresponding to a New Bridge Abutments. 9.17L
-



Session X

“Case Histories of Geotechnical and Hydrological Management and Remediation of Solid, Hazardous and Low-Level Radioactive Wastes, including Liner Cover Systems”

- Y. Sheng
P. Peter
Y. Wei
A. R. Milnes
(Australia)
- Romeo Ciubotariu
Marie Wilson
(Canada)
C. E. Schneeberger
(Switzerland)
William J. Hague
(USA)
- Ronald C. Chaney
Kenneth Demars
Gregory N. Richardson
(USA)
- Niu Zhirong
Zhou Changyong
(China)
- Wayne R. Bergstrom
Patrick Dugan
(USA)
- D. L. Shah
A. V. Shroff
(India)
- F. Colleselli
M. Macoratti
(Italy)
- L.M. Pissarra
N. Guedes
J. Garrido
M. L. Lopes
C. C. Freitas
(Portugal)
- Victor A. Modeer
Mary C. Lamie
(USA)
- Sanjeev Kumar
(USA)
- Capping of an Extremely Soft Neutralised Uranium Tailings
- A Case History in Environmental Geomechanics. 10.01
- The Environmental Remediation of Clark Island -A Former
Allied Signal, Inc. Site. 10.02
- Design of Contaminated Dredged Fills Utilizing Geosynthetics. 10.04
- Case Histories of Two Kinds of Composite Foundation -
Constructing Buildings Over-Crossing Canals. 10.05
- Test Fill to Determine the Compression Behavior of a Closed
Industrial Waste Landfill. 10.07
- Effect of Effluents of Industrial Waste on Soil Properties
(A Case Study of Nandesari Area, Vadodara). 10.08
- A Particular Foundation Problem on a Waste Fill. 10.09
- Alcanena Industrial Waste Landfill - Description of a
Portuguese Case History. 10.10
- Regulatory, Environmental and Geotechnical Solutions to Construction
of a Roadway Embankment over a Landfill. 10.11
- Procedure to Predict Settlement of Solid Waste Landfills Using Power Creep Law.
10.12
-



Session XI

“Case Histories of Non-Destructive Evaluation of Drilled Shafts, Auger Cast Piles and Driven Piles”

Raymond J. Castelli Pile Foundation Construction for the Buckman Bridge
Mohamad Hussein Jacksonville, Florida. 11.01
(USA)

Narong Thasnanipan Sonic Integrity Test on Piles Founded in Bangkok Subsoil
Aung Win Maung Signal Characteristics and their Interpretations. 11.02
Ganeshan Baskaran
(Thailand)

Session XII

SPECIAL SESSION “GEOTECHNICAL ENGINEERING PRACTICE IN THE 21st CENTURY”

Walter W. Hays Toward Earthquake Resilient Cities in the 21st Century:
(USA) Reduction of Community Vulnerability. 12.01



GENERAL REPORTS

- A. J. Lutenegger
Carole L.B. Mitchell
(USA)
Case Histories of Foundations. Paper No. GR-1
- Vlad Perlea
Mary P. Perlea
(USA)
B.B.K. Huat
(Malaysia)
Case Histories of Slopes, Dams and Embankments.
Paper No. GR-II
- Ahmed-W Elgamal
Marshall Lew
(USA)
Case Histories of Geotechnical Earthquake Engineering.
Paper No. GR-III
- George Manyando
Sanjeev Kumar
(USA)
Case Histories of Engineering Vibrations. Paper No. GR-IV
- R. V. Siddharthan
(USA)
Arni E. Rafnsson
(Iceland)
Case Histories of Retaining Structures and Deep Excavations.
Paper No. GR-V
- C. G. Mueller
Baoshan Huang
(USA)
M. Kavvas
(Greece)
Case Histories of Geological, Rock and Mining Engineers
Including Underground Structures and Excavations.
Paper No. GR-VI
- Steven J. Winter
(USA)
Case Histories of Soil Improvement, Grouting, Geosynthetics,
Dynamic Compaction, Vibroflotation, Blasting and other Methods
Including Geo Economics. Paper No. GR-VII
- R.W. Stephenson
(USA)
Case Histories of Forensic Engineering "Where Things Went Wrong".
Paper No. GR-VIII
- Vijay K. Puri
Tom Blackburn
John M. Benson
(USA)
Case Histories of New Solutions to Traditional Geotechnical Problems.
Paper No. GR-IX
- Carsten H. Floess
Mary C. Lamie
W.R. Bergstrom
(USA)
Case Histories of Geotechnical and Hydrological Management
and Remediation of Solid, Hazardous and Low-Level Radioactive
Wastes, including Liner Cover Systems. Paper No. GR-X
-