



Missouri University of Science and Technology
Scholars' Mine

International Conference on Case Histories in
Geotechnical Engineering

(2008) - Sixth International Conference on Case
Histories in Geotechnical Engineering

06 May 1984 - 11 May 1984

First International Conference on Case Histories in Geotechnical Engineering

Multiple Authors

Follow this and additional works at: <https://scholarsmine.mst.edu/icchge>

Part of the Geotechnical Engineering Commons

Recommended Citation

Authors, Multiple, "First International Conference on Case Histories in Geotechnical Engineering" (1984).
International Conference on Case Histories in Geotechnical Engineering. 6.
<https://scholarsmine.mst.edu/icchge/6icchge/session18/>



This work is licensed under a [Creative Commons Attribution-Noncommercial-No Derivative Works 4.0 License](#).

This Article - Conference proceedings is brought to you for free and open access by Scholars' Mine. It has been accepted for inclusion in International Conference on Case Histories in Geotechnical Engineering by an authorized administrator of Scholars' Mine. This work is protected by U. S. Copyright Law. Unauthorized use including reproduction for redistribution requires the permission of the copyright holder. For more information, please contact scholarsmine@mst.edu.



Table of Contents

Theme I

Case Histories in Foundations of Structures and Failure Records

Failure of the Ghana Law School Building in Accra, Ghana	3
N. K. Kumapley, S. Ramachandra—GHANA	
Lakeview Tower: Case History of Foundation Failure	7
K. R. Peaker—CANADA	
Moisture Induced Damages to Building Foundations.....	15
S. S. Bandyopadhyay, R. Reuss—U.S.A.	
Soil Conditions and Foundation Problems in the Desert Regions of the Middle East.....	21
A. S. Stipho—SAUDI ARABIA	
Damaging Settlements of a Building due to Gypsum Dissolution.....	27
M. P. Luong—FRANCE	
Bearing Capacity of Piles Under Long-Term Vibration.....	31
Xu You Zai, Liu Yao Fu, Shi Yul Iang, Xin Su Lan—CHINA	
Settlement Observations on Two Mat Foundations.....	37
E. Winter, P. Chung—U.S.A.	
Caisson Design by Instrumented Load Test	41
D. J. Lane—U.S.A.	
Grouting to Control Deep Foundation Settlement.....	51
B. McClelland, E. J. Ulrich—U.S.A.	
Performance of Large Diameter Oil Storage Tanks	61
I. K. Ozaydin, S. Y. K. Inan—SAUDI ARABIA	
Behaviour of Bridge Abutment on Fractured Chalk	67
A. P. Butcher, A. Marsland—UNITED KINGDOM	
Power Station Foundations in Deep Expansive Soil	77
G. E. Blight—SOUTH AFRICA	
Recovering Differential Settlements by Vertical Drains.....	87
C. Mastrantuono, A. Tomiolo, E. Arcangeli—ITALY	
Vertical Load Tests of Footings on Silt	93
D. P. LaGatta, T. O. Keller—U.S.A.	



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Negative Friction and Lateral Loading on Piles	101
E. E. De Beer, M. Wallays, E. Goelen—BELGIUM	
Geotechnical Problems and Performance Studies - Chilla Power Scheme, Hardwar	105
D. N. Bhargava, Dwarka Nath, S. N. Kapoor, Sunder Singh—INDIA	
Settlement of a Building Founded on Difficult Soil	111
Iqbal H. Khan, Fathi M. Layas—LIBYA	
Ground Heave Due to Pile Driving.....	117
J. P. Dugan Jr., D. L. Freed—U.S.A.	
Geologic Considerations in Civil Constructions - Malaysian Case Studies	123
Boon K. Tan—MALAYSIA	
Observation and Analysis of Settlements of Oil Tanks on High Compressive Saturated Soft Clay	127
Zhang Yongjun—CHINA	
Evaluation of a Differentially Settled Tank	133
S. M. Gazioglu, J. L. Withiam—U.S.A.	
A Combined Earth and Rock Bearing Foundation - Hospital Humana Mexico City D. F.....	143
L. E. Wilson, Michael R. Stomer, Pablo Girault—U.S.A.	
Tower Foundations Bearing Above Weak Soils	151
T. J. Kaderabek, D. Barreiro, M. A. Call—U.S.A.	
Foundation Design and Construction for a Large Mill Complex	157
C. R. I. Clayton, J. Milititsky, L. J. L. Carvalho—UNITED KINGDOM	
Effect of Foundation Deformations on the Damage of a Masonry Villa (Case History)	165
S. A. Abo-El Magd, H. M. Hosny, M. Mashhour—EGYPT	
A New Version of Rectification for the Leaning Structures and Foundations	169
Yi-Ji Wang, Jian-Xin Yuan—CHINA	
Deformation of Slopes of Two Excavations in Soft Clays	173
C. W. Sheng—CHINA	
Field Observation of Pore Pressure in Soft Clay.....	179
R. L. Wei—CHINA	
Settlement of a One Floor Building on Soft Clay Beside a Heavy Building	185
Mohamed A. El-Sohby, Ossama Mazen—EGYPT	
Prediction of Axial Pile Capacity Based on Case Histories	191
R. E. Olson, N. D. Dennis, D. G. Winter—U.S.A.	
Foundation Performance of Very Old Structures	201
S. C. Handa—INDIA	



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Philip Morris Corporate Headquarters Building.....	209
A. J. Ciancia, H. M. Horn—U.S.A.	
Chimney Foundation on Drilled Piers	217
K. Y. C. Chung, L. D. Cundy—U.S.A.	
Adjustable Columns Control Settlement of Structure	223
F. B. Newman, A. M. Digioia, Jr.—U.S.A.	
Design Considerations and Long-Term Performance of a Building Foundation in Clay	229
G. E. Bauer—CANADA	
Monitoring and Performance of a Bridge Abutment.....	235
G. Y. Felio, G. E. Bauer—CANADA	
Foundation Problems and Solutions at the Bridge River, Powerhouse No. 1	241
H. Taylor, A. P. Joseph—CANADA	
Raymond Concrete Cylinder Piles in Arabian Gulf	249
P. D. Engeling, R. F. Hayden, R. A. Hawkins—U.S.A.	
Foundation Heave at ASCO II Nuclear Power Plant.....	259
R. B. Fallgren, C. R. McClure—U.S.A.	
Settlement Experienced at a Recently Licensed Nuclear Station	267
J. T. Chen, L. W. Heller—U.S.A.	
Tank Farm Construction Over Soft Organic Clays - A Case History.....	271
Syed Ahmed—U.S.A.	
Embankment on Vertical Drains - Pore Pressures During Construction	275
M. Jamiolkowski, R. Lancellotta—ITALY	
Power Line Foundation Design Using the Pressuremeter	279
J. L. Briaud, A. J. Pacal, A. W. Shiveley—U.S.A.	
Non-Negative Skin Friction Piles in Layered Soil	285
S. L. Lee, G. P. Karunaratne, S. Sithichaikasem—SINGAPORE	
Excessive Settlement in Buildings	289
A. Verghese Chummar—INDIA	
Structural Fill of Steel Slag Caused Heave of a Building	295
Janardanan O. Uppot—U.S.A.	

Theme II

Case Histories in Retaining Structures and Failure Records

Monitoring of a Deep Basement in London	301
L. A. Wood, A. J. Perrin—UNITED KINGDOM	



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Predicted and Observed Lateral Deformations of Anchored Retaining Walls	309
Tj. Kooistra, F. L. Beringen—THE NETHERLANDS	
Stability Problems in a Deep Excavation in Clay	315
Gunnar Aas—NORWAY	
Field Experience on Corrugated Metal Culverts.....	325
P. Habib, M. P. Luong, N. T. Long, G. Legeay, A. Millian, L. Baude—FRANCE	
Braced Cofferdam to Improve Spillway Stability During Rehabilitation	331
Rodney M. Wong, James T. Passage, Sami S. Naami—U.S.A.	
Repair of a Reinforced Earth Wall	335
Long, Livet, Boutonnet, Marchal, Olivier, Nabonne, Plaut—FRANCE	
The Pathology of Metal Culverts	341
N. T. Long, A. L. Millan—FRANCE	
Behavior of Braced Cut in Connection with Construction of Large Underground Station.....	347
S. Uchida, H. Ito, T. Kaino, H. Tarumi—JAPAN	
Earth Pressure on Retaining Walls and Buried Pipes	355
M. Fukuoka, Y. Imamura—JAPAN	
Thrust Evolution on the Shoring of Two Large Excavations in Geneva	363
A. Fontana—SWITZERLAND	
Field Behavior of Retained Earth Structure	371
Z. Al-Yassin, C. K. Shen—U.S.A.	
Use of Ground Anchors in Residual Soils	377
R. Kannan, Bengt B. Broms—SINGAPORE	
Load Measurements of an Anchored Retaining Wall	387
P. Rocha Filho, N. M. Zeitoune—BRAZIL	
Failure of an Anchored Sheetpile Bulkhead	393
D. P. LaGatta, D. R. Shields—U.S.A.	
Anchor Slab Retaining Wall Stands Overtopping Flood.....	401
Z. L. Wang, X. M. Wu, Z. S. Zhang—CHINA	
Performance of a 30 m Deep Instrumented Diaphragm Wall	405
M. M. Soares—BRAZIL	
Failure of a Small Gravity Dam and the Repair	411
David F. McCarthy—U.S.A.	
Permanent Tieback Retention System.....	417
T. C. Anderson, M. E. Lockwood, M. F. Nethero—U.S.A.	



Theme V

Case Histories in Geotechnical Earthquake Engineering

Liquefaction Potential Evaluation for Arcadia Dam.....	425
J. R. Wagner—U.S.A.	
Pile Foundation under Liquefied Soils	433
Liu Huishan, Qiao Taiping—CHINA	
Liquefaction Risk Evaluation During Earthquakes.....	445
Qiao Taiping, Wang Chenchun, Weng Lunian, Liu Huishan—CHINA	
Liquefaction Potential of a Silty Sand Site	455
H. Dezfulian, N. D. Marachi—U.S.A.	
Research on the Permeability and Earthquake Damage of An Earth Dam Foundation.....	459
Zhi-Jie Zhu, Wen-Kai Liu—CHINA	
Prediction of Pore Water Pressure During Earthquakes in Southern Kyoto Area.....	469
F. Oka—JAPAN	
A Geotechnical Study for Land-use Planning Purposes.....	475
F. Ciuffi—ITALY	
Seismic Response and Liquefaction Analysis by an Approximate Method	481
M. Hyodo, T. Yamanouchi, J. Hashizume—JAPAN	
Verification and Evaluation of the Result of Liquefiable Soil Treated with Vibroflotation	485
Gu Bao-he, Hu Zong-han, Wang Wan-yu—CHINA	
Seismic Motion Selection Criteria for Dam Design	491
G. Rodolfo Saragoni—CHILE	
Behavior of Some Earth Dams on Liquefiable Soil.....	499
A. Popovici, V. Perlea, I. Corda—ROMANIA	
Earthquake Damages to Earth Dams and Levees in Relation to Soil Liquefaction and Weakness in Soft Clays	511
W. S. Wang—CHINA	
Surface Damage of Tangshan Earthquake and Characteristics of Response Spectrum of Ground Movement	523
S. D. Zhao, H. Q. Fang—CHINA	
A Comparison of Methods of Estimating the Attenuation of Earthquake Strong Ground Motion	531
O. W. Nuttli, R. B. Herrmann—U.S.A.	
Assessment of Earthquake Size from Rock Fracture Dimensions of Seismic Source in Geotechnical Earthquake Engineering Investigations	535
L. S. Srivastava—INDIA	



Table of Contents

Theme III

Case Histories in Dams, Embankments and Slopes

Powerhouse Slope Behavior, Fort Peck Dam, Montana	541
J. V. Hamel, G. S. Spencer—U.S.A.	
Grand Coulee Riverbank Stabilization - Case History of the Design of Remedial Measures	553
J. Lawrence Von Thun—U.S.A.	
Peculiar Behaviour of the Manicouagan 3 Dam's Core.....	561
O. Dascal—CANADA	
The Santa Helena Dam on Compressible Foundation	569
Vinod K. Garga, Arnoldo V. Rocha, Homero G. Ramos—CANADA	
Clay Shale Foundation Slide at Waco Dam, Texas.....	579
W. R. Stroman, R. R. W. Beene, A. M. Hull—U.S.A.	
The Use of Limited Field Observation in Remedial Design.....	587
J. P. Sully, G. I. McPhail—VENEZUELA	
Design and Performance of Horizontal Drains.....	593
J. H. Kleppe, G. M. Denby—U.S.A.	
Performance of Trial Embankment on Soft Clay.....	599
T. Shibata, H. Sekiguchi—JAPAN	
Embankments Built Over Swamps	609
Samuel Y. Ng, James C. Rudd—U.S.A.	
Stability of Slopes - A Case History	619
G. Ramasamy, Gopal Ranjan, Bhawani Singh, A. C. Khazanchi, U. N. Sinha—INDIA	
Performance of an Embankment on Peat.....	625
R. E. Olson—U.S.A.	
Stability of Hill Slopes and Foundation Condition at Radio Astronomy Centre Ootacamand	631
R. K. Katti, V. S. Chandrasekaran, A. Parthasarathy, K. K. Moza—INDIA	
An Embankment on Soft Clays with Sand Drains.....	637
A. Cancelli, A. Cividini—ITALY	
Controlled Breaching of a Full Scale Clay Flood Bank	645
A. Marsland—UNITED KINGDOM	



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Deep Seated Base Failure and Reconstruction Work	655
M. Fukuoka—JAPAN	
Collapsible Soils Chashma Right Bank Canal	665
Izharul Haq—PAKISTAN	
Failure of a Dredged Slope in a Sensitive Clay.....	671
D. P. LaGatta, S. L. Whiteside—U.S.A.	
The Delayed Failure of a Large Cutting in Hong Kong	679
R. R. Hudson, S. R. Hencher—HONG KONG	
The Failure of a Cut Slope on the Tuen Mun Road in Hong Kong	683
S. R. Hencher, R. P. Martin—HONG KONG	
The Failure of a Soil Blanket Lining Caused by the Action of Bacteria.....	689
G. W. Plant, P. B. B. Voslo—SOUTH AFRICA	
Failure Slope in Clay Shales in Aratu Bay - Brazil	695
R. B. Guimarães—BRAZIL	
Failure of an Embankment on Soft Clay	701
M. K. Yegian, Hugo Perez Lasalvia—U.S.A.	
The Foundation of the Right Bank in Wadi-Zarat Dam	707
M. A. Benltayf, M. Atalla, K. Rabah—LIBYA	
Lake Monona Causeway - Madison, Wisconsin, USA	713
W. W. Warzyn, C. A. Stoll—U.S.A.	
Sealing Leakage of Earth Dam by Concrete Diaphragm.....	721
Shen Chonggang, Jiang Guocheng—CHINA	
Behaviour of Ramganga Dams	725
Bhagwat V. K. Lavania—INDIA	
Failure of Micaceous Waste Tailings Dam	731
W. F. Brumund—U.S.A.	
Performance of a Stone Column Supported Embankment.....	735
R. R. Goughnour, R. D. Barksdale—U.S.A.	
Slide Stabilization with Gravel Trenches	743
E. G. Wardlaw, L. A. Cooley, A. E. Templeton, R. L. Fleming, Jr.—U.S.A.	
Long Term Failure in Compacted Clay Slopes	749
A. E. Templeton, G. L. Sills, L. A. Cooley—U.S.A.	
Stability of an Erratic Tailings Deposit	755
P. C. Kotzias, A. C. Stamatopoulos, B. Karas—GREECE	
The Stability of Shannon Embankments	759
K. R. Massarsch, M. O. Fives—SWEDEN	



Theme IV

Case Histories in Off Shore Structures

- Rock Borer Attack on Juaymah Trestle Concrete Piles 767
 E. A. Wiltsie, W. C. Brown, K. Al-Shafei—SAUDI ARABIA

Theme VI

Case Histories in Machine Foundations

- Machine Foundations in Power Plant and Other Industries - Case Studies 775
 K. G. Bhatia—INDIA
- Dynamic Response and Static Analysis of RCC Space Frames Supporting High Speed Centrifugal Machines with Coupled Soil-structure Interaction 781
 Dilip K. Chakravorty, Dhiman K. Ghosh, H. N. Batavyal—INDIA
- A Case Study on Decreasing Vibration of Machine Foundations and Structures 787
 Wang Xikang—CHINA

Theme VII

Case Histories in Rock Mechanics

- Shale Pit Slopes - A Case History 793
 D. H. Shields—CANADA
- Stillwater Tunnel, Central Utah Project, Utah, Case History 807
 R. S. Sinha, K. D. Schoeman—U.S.A.
- Pittsburgh's Mt. Lebanon Tunnels - A Case History 817
 G. L. Butler, B. P. Cavan, F. K. Mussger, G. W. Rhodes, H. T. Whitney—U.S.A.
- Mechanised Rock Tunneling in Adverse Conditions 827
 I. McFeat-Smith—HONG KONG
- The Experience of a Dam Founded on Difficult Rock Foundation 833
 Jian-Yun Mei, Yu-Yin Guo—CHINA
- The Stability of Underground Power Chambers in Brittle Rock 843
 Weishen Zhu, Kejun Wang, Guangzhong Peng—CHINA
- Geotechnical Problems in a Bridge over Corinth Canal 849
 S. G. Christoulas, N. A. Kalteziotis, G. K. Tsiambaos—GREECE
- Research on Slope Stability of a Certain Open-Pit Mine 855
 Wang Wuling—CHINA



Theme VIII

Case Histories in Selection of Sites for Industrial Structures and Determination of Design Soil Parameters

Study on Vibration in Site Selection for a Precision Instrument Factory	863
Pan Fulan—CHINA	
A Dockwall Failure in Milwaukee, Wisconsin	869
A. B. Wagner—U.S.A.	
A Case of Singular Geotechnical Failure for Industrial Structures in the Peruvian Andes	877
A. Carrillo Gil, R. Torres Vega—PERU	
Siting Study for Aluminum Plant in Central Kentucky	885
Grover C. Cox, III—U.S.A.	
A Case of Land Use and Urban Planning in the Expansive-Soil District	895
Hou Shitao, Wang Siyi, Zhou Jibing, Cao Kezhi—CHINA	
Siting for a Nuclear Power Plant in Saudi Arabia	901
A. A. Sabtan, W. M. Shehata—SAUDI ARABIA	

Guest Lectures

Case Histories for Today's Geotechnique.....	907
R. B. Peck—U.S.A.	
Foundations on Friction Creep Piles in Soft Clays.....	913
Sven Hansbo—SWEDEN	
Behavior of Two Big Rockfill Dams, and Design Aims	923
V. F. B. de Mello—BRAZIL	
Time Dependent Limit Stability of Tunnel and Dam Engineering in Difficult Rocks.....	943
Tan Tjong Kie—CHINA	
The Brenda Mines' Cycloned-Sand Tailings Dam	953
Earle J. Klohn—CANADA	



Table of Contents

Guest Lecture

A Case History of Bridge Performance During Earthquakes in Japan	981
T. Iwasaki—JAPAN	

Theme I

Case Histories in Foundations of Structures and Failure Records

Lateral Pile Response from Model Tests in a Large Centrifuge	1011
Y. O. Barton, R. H. G. Parry, W. D. Liam Finn—U.K.	
Down Drag on an Instrumented Bored Pile in Soft Clay	1019
R. K. Bhandari, M. R. Soneja, Devendra Sharma—INDIA	
Stability of Suspension Bridge Anchorage System	1027
Gopal Ranjan, Shamsher Prakash, Swami Saran, Bhawani Singh—INDIA	
Settlement of Three Grain Tanks on Alluvial Soils Exhibiting Desiccation Profiles	1033
S. R. Saye—U.S.A.	
Dynamic Precompression Treatment—A Case History	1041
F. J. Leon—U.S.A.	
Settlement Performance of a Mat Foundation on Unsaturated Loess	1053
Alan J. Lutenegger, Bernard D. Remmes, Leo D. Handfelt—U.S.A.	
Power Plant Construction on a Thick Sand Deposit.....	1059
A. Arcones, A. Soriano—SPAIN	

Theme II

Case Histories in Retaining Structures and Failure Records

Damage and Remedial Measures for Buildings on Hill Slopes	1071
Swami Saran, Gopal Ranjan, Bhawani Singh, A. S. R. Rao—INDIA	



Theme III

Case Histories in Dams, Embankments and Slopes

Slip Failure of Embankment on Soft Marine Clay	1079
K. Y. Yong, S. T. Ting—SINGAPORE	
Evolution of Design and Construction of Lornex L-L Tailings Dam	1083
M. D. (Dal) Scott, Robert C. Lo—CANADA	
Efficacy of Grout Curtain at Ramganga Dam	1089
M. C. Goel, B. N. Sharma—INDIA	
Earth Dams at Nuclear Power Plants	1093
R. Pichumani, D. C. Gupta, L. W. Heller—U.S.A.	
Performance of Some Embankment Dams in India	1097
T. Ramamurthy—INDIA	
Reconsideration of Failure Initiating Mechanisms for Teton Dam	1103
G. A. Leonards, L. W. Davidson—U.S.A.	

Theme V

Case Histories in Geotechnical Earthquake Engineering

Liquefaction of a Soil Deposit During an Earthquake	1117
M. K. Gupta, Shamsher Prakash—INDIA	
Assessment of Seismic Stability of Earth Dams by Comparative Methods	1123
Rodney J. Huang, Marshall L. Silver—U.S.A.	
Post-Earthquake Failure of a Tailings Dam Due to Liquefaction of the Pond Deposit	1129
Kenji Isha—JAPAN	

Theme VI

Case Histories in Machine Foundations

Vibration Studies of Block Type Machine Foundations	1147
S. K. Guha—INDIA	
Forge Hammer Foundation on Dilative Soil	1155
S. J. Yang—CHINA	
Foundation-Rearing-Rotor Interaction Problem in Controlling Vibrations in a 120 mw Turbo-Generator	1157
Krishen Kumar, Shamsher Prakash—INDIA	



Theme VIII

Case Histories in Selection of Sites for Industrial Structures and Determination of Design Soil Parameters

- Geotechnical Investigations for Foundation Design for Multi-storeyed Building 1167
 S. C. Handa, Swami Saran, G. Ramasamy, A. S. R. Rao, B. Parkash—INDIA

Theme IX

Miscellaneous Case Histories

- A Case History of Chemical Attack of a Clay Shale 1175
 G. H. Glos, D. Hinkle—U.S.A.
- Design and Construction of a Railway Yard, Embankment and Foundations Under Difficult Groundwater Conditions 1183
 Hari D. Sharma, S. Sengupta, Glen Harron—CANADA
- Preloading for Large Storage Building 1191
 A. C. Stamatopoulos, P. C. Kotzias—GREECE
- Densifying a Landfill for Commercial Development 1195
 S. B. Steinberg, R. G. Lukas—U.S.A.
- Dykes on Clay Foundation at Bersimis 2 1201
 S. Z. Akber—CANADA
- Design of Road Cut Adjacent to Existing Structure 1209
 G. C. Whited, C. N. Laughter—U.S.A.
- A New Method of Stabilization of Soft Soils 1215
 M. A. Aziz—SINGAPORE
- Ground Movement Characteristics Above Mined Panels in Appalachia - An Empirical Approach 1221
 M. Karmis, T. Triplett, P. Schilizzi, G. Hasenfus—U.S.A.
- Performance of Preload on Cohesionless Soils 1229
 A. F. Youssef, O. Erol—SAUDIA ARABIA
- Performance of Sand Drains in a Tidal Marsh 1235
 R. P. Long, W. H. Hover—U.S.A.
- Geotechnical Aspects of the Fort McHenry Tunnel - Design and Construction 1245
 S. K. Sarkar, G. A. Munfakh—U.S.A.



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Case History on Dewatering Problems in Shanghai	1255
L. X. Shi—CHINA	
In Situ Stabilization of Two Industrial Sites by Dynamic Compaction	1259
John F. O'Brien, Charles P. Gupton—U.S.A.	
The Behavior of House on Seasonally Frozen Ground	1265
Xu You Zai, Wang Zheng Qiu—CHINA	
Settlements Induced by Soft Ground Tunneling	1269
Miguel P. Romo—MEXICO	
Unplanned Construction of a 210 Ft High Temple	1281
Gopal Ranjan, Shamsher Prakash—INDIA	
Slurry Trench Wall Replaces Structure Underpinning	1287
E. J. Zeigler, J. L. Wirth, J. R. Miller—U.S.A.	
Ground Improvement for Oil Tank Farm in Indonesia	1297
A. F. Abbs, J. M. Cognon, R. W. N. Kelsey—U.K.	
Twenty-Year Performance of Soil-Cement Dam Facings	1307
T. J. Casias, A. K. Howard—U.S.A.	
Foundation Movement Monitoring of Heavy Structures - A Case History	1313
M. R. Lewis, A. Sanver—U.S.A.	
Dewatering of the Construction Site for a 200-Foot Diameter Clarifier Tank Founded on Sand and Gravel	1319
Grover C. Cox—U.S.A.	
Failure of Salt-Aragonite Storage Pad	1329
Yong S. Chae—U.S.A.	
Performance of Diaphragm Walls in Deep Foundation Excavations	1335
Z. C. Moh, T. F. Song—CHINA	
Stabilization of the Oudenberg Hill in Geraardsbergen.....	1345
R. De Paepe, M. Wallays—BELGIUM	
Movements Around Transit Tunnels in Mixed Ground.....	1351
L. Edgers, D. E. Thompson, J. S. Mooney, L. W. Young, Jr.—U.S.A.	
Effectiveness of a Slurry Cutoff Wall at Loeffel Site	1361
G. W. Lee, Jr., S. K. Bhatia, G. A. Swenson, III, S. P. Clemence—U.S.A.	
Improvement of a Dumped Rockfill Foundation by Dynamic Consolidation	1365
Adrian Wightman, Nelson F. Beaton—CANADA	
Upgrading Existing Footings with Micro-Piles.....	1373
Surinder Singh, E. Itzig Heine—U.S.A.	



**Proceedings: First International Conference on Case Histories in Geotechnical Engineering, St. Louis, Missouri,
May 6-11, 1984.**

Highway Interchange Constructed with Slurry Walls	1385
E. Itzig Heine, Frank A. McDonough, Surinder Singh—U.S.A.	
Construction of Key Lake Tailings Facility	1393
R. B. Knight, J. P. Haile—CANADA	
India's First Venture Relating to Subsurface Drainage by Horizontal Drains	1401
T. K. Natarajan, A. V.S.R. Murty, Deep Chandra—INDIA	
Uranium Mill Tailings Geotechnical Investigations—A Case History	1405
V. Singh, J. B. Berry, D. F. Kapral—U.S.A.	
Dewatering, Hydraulic Failure and Subsequent Analysis of a Sheeted Excavation.....	1415
G. E. Bauer—CANADA	
Expansive Soil Pavement Design Using Case Studies	1421
G. R. McKeen, R. L. Lytton—U.S.A.	
Soft Ground Tunnel Failures in Michigan.....	1429
Jerome C. Neyer—U.S.A.	
Case History—Hyperbolic Cooling Tower Foundation	1435
L. J. Almaleh—U.S.A.	
Subsidence Affects Due to Gypsum Solution in Syracuse, New York	1439
G. W. Lee, S. P. Clemence, S. K. Bhatia, S. Anagnos—U.S.A.	
Direct and Indirect Influence of Mining Related Subsidence on Structural Damages—A Case Study	1443
H. J. Siriwardane, L. K. Moulton—U.S.A.	
The Creation of Additional Space for the Storage of Dredged Materials— A Case History	1447
Nicholas Chryssafopoulos—U.S.A.	
Ground Response, Baltimore Lexington Market Tunnels	1451
J. G. Engels, S. J. Calabrese—U.S.A.	
Mechanism of Dynamic Consolidation and Its Environmental Effect.....	1459
Wang Zhong-qi, Deng Xiang-lin—CHINA	
Pretreatment of a Soft Soil by Surcharging—A Case History	1467
D. Lakner, I. K. Lee, E. Armstrong, O. G. Ingles—AUSTRALIA	
Instrumentation of a Sewer Tunnel in Weak Singapore Soils.....	1473
K. W. Lo, G. P. Karunaratne, S. L. Lee—SINGAPORE	